

 Pressing pressure and filling more than 100 kgf is DANGEROUS!

Pressing pressure and filling more than 100 kgf is DANGEROUS!



Leaning over the Keg is Dangerous!



Danger!

- Tilting
- Dropping
- Throwing



Danger!




Contact of keg with alkali is dangerous!



Pouring with CO₂ pressure higher than 3 bar is Dangerous!




Transportation is only possible in the box



Should be carried by two people only.



Do not store exposed to the sun and near heating devices.



Do not move the filled kegs on slippery floors.

